

Damaged RotorWay Exec 162F N3213K



Helicopter damaged from hard roll-over to left from 2 ft. hover.

Undamaged Components:

- Engine
- Electrical, Cooling, Oil and Fuel Systems
- Landing Gear Cross Struts
- Tail Rotor
- Instruments, Avionics
- Cyclic and Collective Controls
- Fiberglass Panels Aft of Tanks, on Right Side and Strut Covers
- Tail Rotor Drive
- Fuel Tanks
- Floor pan & Instrument Pod

New Components:

- Original RotorWay Main Rotor Blades (still in crate)
- Premium Quality (Gates) Replacement Engine Belts

Components Damaged, But Repairable:

- Frame
- Fiberglass Panels Left Side, Forward of Tanks and Tub
- Instrument Panel
- Tail Rotor Pitch Control
- Tail Rotor Pitch Control Cable
- Seat Bulkhead

Extras Included:

- Bruce's Custom Cover for Bubble and Blade Tips
- Auxiliary Ground Handling Wheel Bar for Attachment to Front Tips of Skids
- Blue Streak Governor
- Pro-Drive Cog Belt Drive
- Pro-Drive RPX DynaVibe Balancer
- Auxiliary 12 volt Source Socket in Cabin
- Convenient Access to Battery Terminals in Cabin
- Pointer ELT
- Electric Blower for Cooling/Heating Cabin and Windscreen
- Navigation and Landing Lights
- Altered Collective Grip for Increased Knuckle Room
- Appliance for Convenient Main Rotor Balancing
- *Cerakoted* Exhaust Manifold Pipes

Components Irreparably Damaged Needing Replacement:

- Main Rotor Shaft Assembly
- Secondary Shaft
- Windscreen and Left Eyebrow Window
- Skids
- Tail Cone
- Vertical and half of Horizontal Stabilizers